10/7/2015								
		Consiss contor						
Status of Pole Repl	acements in St Cloud S	service center						
ResponsibleParty:	Northwest							
YearComplete:	Current Work Load							
Count of Status			Status					
						Install		
						complete-	Already	
			Assigned to	Design	Sent to	Old pole	completed	Grand
AssignedContracto	ServiceCenter	INSPECTLOCATION	design	complete	construction	removed	by others	Total
Local	Saint Cloud	MN- Northwest- Saint Cloud- Kimball				1	1	2
		MN- Northwest- Saint Cloud- Kingston				3		3
		MN- Northwest- Saint Cloud- Le Sauk township			1			1
		MN- Northwest- Saint Cloud- Munson township				3		3
		MN- Northwest- Saint Cloud- Saint Cloud	26	2	19	119		166
		MN- Northwest- Saint Cloud- Sartell			2			2
		MN- Northwest- Saint Cloud- Waite Park			1	. 17		18
	Saint Cloud Total		26	2	23	143	1	195
Local Total			26	2	23	143	1	195
Grand Total			26	2	23	143	1	195

